STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155752	A. BUILDING **01** B. WING _____	R **03/13/2014**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
MORNINGSIDE NURSING AND MEMORY CARE CENTER	**18325 BAILEY AVE** **SOUTH BEND, IN 46637**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/10/14 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 03/13/14 Facility Number: 004732 Provider Number: 155752 AIM Number: 200808300 Surveyor: Dennis Austill, Life Safety Code Specialist At this PSR survey, Morningside Nursing and Memory Care Center was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 18, New Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with automatic smoke detection in the corridors, in areas opened to the corridors, and battery operated smoke detectors in resident rooms 110, 111, and 114 with hard wired smoke detectors in the other fourteen resident sleeping rooms. The facility has a capacity of 40 and had a census of 37 at the time of this survey. All areas where residents have customary access were sprinklered. All areas providing facility	{K 000}		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155752	A. BUILDING **01** B. WING _____	R **03/13/2014**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
MORNINGSIDE NURSING AND MEMORY CARE CENTER	**18325 BAILEY AVE** **SOUTH BEND, IN 46637**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 1 services were sprinklered with the exception of a wood shed. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 03/17/14.	{K 000}		